

कार्यालय , कार्यपालन अभियंता , लोक स्वास्थ्य यांत्रिकी विभाग  
कवर्धा , जिला-कबीरधाम

क्र./ लो.स्वा.या.वि./2022/कवर्धा 8998

दिनांक 8/12/2022

**SAFE DRINKING WATER AND SANITARY CONDITION CERTIFICATE**

It is certified that an inspection team headed by D.S. Rajput. A.E.  
PHE Sub Dn. Kawardha. (Name of Officers  
with designation) from PHE D (Name of  
Department/Office) inspected the **Kendriya Vidyalaya Maharajpur Kawardha ,  
Karpatri Stadium, Jila Panchayat Road , Kawardha (Chhatisgarh)** (Name &  
Address of the School) on 08/12/22 and found that the **Kendriya Vidyalaya  
Maharajpur Kawardha , Karpatri Stadium, Jila Panchayat Road , Kawardha  
(Chhatisgarh)** (Name of school) has safe drinking water facilities for the students and  
members of staff of the institution and is maintaining the hygienic sanitation condition in  
the school building & the campus as per the norms prescribed by the Central/State/U.T  
Govt.

The above certificate is valid for a period of One years w.e.f. 08/12/22.

Signature with Seal : [Signature]  
Assistant Engineer  
Public Health Engg. Sub Dn.  
Name : Kawardha (C.G.)  
Designation : \_\_\_\_\_

[Signature]  
8/12/22  
S.D. Sankuare S/S  
Kawardha

[Signature]  
Executive Engineer  
Public Health Engineering  
Distt-Kabirdham (C.G.)